




# X-am 8000

Dräger







Any use of the device requires full understanding and strict observation of the Instructions for Use of the device.



This Quick User Guide does not replace the Instructions for Use of the device!

## ON

## OFF









..... <100%






———— 100%



.....



Optional




08:33	BT	75%
iBut	0.0	ppm
ch <sub>4</sub> +	10.0	%LEL
CO <sub>2</sub>	0.3	Vol%
O <sub>2</sub>	20.9	Vol%
CO	0.0	ppm
H <sub>2</sub> S	0.0	ppm
H <sub>2</sub>	0.0	%LEL




# Don't print this page


# Diese Seite nicht drucken




X-am 8000


Dräger










Warning




Battery low!











Switching off...



0 %

Battery empty!



90 33 806 - EB 4836.300

© Dräger Safety AG & Co. KGaA

Edition 01 - June 2017

Subject to alteration

Safety AG & Co. KGaA

Revalstraße 1



23560 Lübeck, Germany

Tel +49 451 882 0

Fax +49 451 882

www.draeger.com


A4 folded to A5



Colores/ Farben in CMYK

- 100, 60, 0, 6,
- 18, 12, 14, 0
- 29, 21, 21, 3
- 0, 0, 0, 30
- 0, 95, 92, 0
- 10, 0, 95, 0
- 36, 7, 83, 0
- 69, 1, 13, 0

**i** Any use of the device requires full understanding and strict observation of the Instructions for Use of the device.  
**📖** This Quick User Guide does not replace the Instructions for Use of the device!



	
	
	
	$C_6H_6$ 

-----  
 Cutting line  
 Schnittkante

-----  
 Folding line  
 Falzkante